

Keep away from this PTO shaft

TYTAN

## Not Safe

PTO shaft is bad angle at joint

**Bad for tiller** to lean back

Saturday, April 25, 2009



### Keep tiller brackets vertical



Vertical Is best

### Level or Forward is best





THE.







Rip the ground first up and remove the rocks. Saves your equipment. Ask your Dealer





# Do NOT Over fill

#### Fill Hole Oil level check hole

Fill Level is 50% - with 80-90 W Gear oil







